

STEEL AND PIPE SUPPLY

SPS Coil Processing Houston
8500 Clinton Drive
Port of Houston Gate 1 Road
Houston, TX 77029

METALLURGICAL TEST REPORT

PAGE 1 of 1
DATE 06/14/2023
TIME 07:40:22

S
O
L
D
T
O

S
H
I
P
T
O
17238
Longview Warehouse
4750 West Marshall Ave
Longview TX 75604-4817

Order	Material No.	Description	Quantity	Weight	Customer Part	Customer PO	Ship Date
40405086-0010	7518848120	3/16 48 X 120 A786 FLOOR PLATE	13	4,529.200			06/13/2023

Chemical Analysis

Heat No. B304359		Vendor STEEL DYNAMICS COLUMBUS					DOMESTIC					Mill STEEL DYNAMICS COLUMBUS			Melted and Manufactured in the USA		
Carbon	Manganese	Phosphorus	Sulphur	Silicon	Nickel	Chromium	Molybdenum	Boron	Copper	Aluminum	Titanium	Vanadium	Columbium	Nitrogen	Tin		
0.0600	0.3200	0.0140	0.0030	0.0300	0.0400	0.0800	0.0200	0.0001	0.1100	0.0320	0.0010	0.0010	0.0000	0.0060	0.0050		

Mechanical / Physical Properties

Mill Coil No. 23B718180	Tensile (PSI)	Yield (PSI)	% Elong (2 in)	Rckwl	Grain	Charpy	Charpy Dr	Charpy Sz	Temperature	Olsen
Batch 1001344875 13 EA 4,529.200 LB										

THE CHEMICAL, PHYSICAL, OR MECHANICAL TESTS REPORTED ABOVE ACCURATELY REFLECT INFORMATION AS CONTAINED IN THE RECORDS OF THE CORPORATION.
The material is in compliance with EN 10204 Section 4.1 Inspection Certificate Type 3.1

This test report shall not be reproduced, except in full, without the written approval of Steel & Pipe Supply Company, Inc.